

Overhead Tunnel Kit for Solar-ready Combination Service Entrance Device (CSED)

Cat. No. LOTKx

LEVITON®

PK-A3306-10-00-5A

WARNINGS

- **TO AVOID FIRE, SHOCK, OR DEATH, TURN OFF ALL POWER SERVICING THE DEVICE, TEST THAT POWER IS OFF BEFORE SERVICING OR WIRING** and ensure connections are made in the same sequence as existing device connections.
- This equipment **MUST BE** installed and serviced by a qualified electrician.
- Leviton circuit breakers **MUST BE** used with a Leviton circuit breaker enclosure.
- Before providing power to the load center, check all electrical connections and confirm that the wiring is correct.
- Replace all doors and covers before connecting power to this equipment.

CAUTIONS

- Use **ONLY** approved fittings and clamps to avoid damage to wires.
- Ensure that all branch circuit breakers are in the **OFF** position before installing into the panel.
- To be installed and/or used in accordance with electrical codes and regulations.
- Use this device only with copper or copper clad wire.

INSTALLATION

ENGLISH


Installation

WARNING: TO AVOID FIRE, SHOCK, OR DEATH, TURN OFF ALL POWER SERVICING THE DEVICE, TEST THAT POWER IS OFF BEFORE SERVICING OR WIRING and ensure connections are made in the same sequence as existing device connections.

NOTE: Overhead tunnel is to be used only for top feed wiring.

1. Remove Compartment Covers

NOTE: To remove the deadfront, refer to the panel instruction sheet.







2. Remove Knockouts for Top Feed Wiring

NOTE: Before removing any knockouts from the enclosure, consult the local electrical code to determine the knockout requirements.

a. Strike the center of the knockout.

b. Pry each ring up one at a time with a pair of pliers.


c. Grip both ends with the pliers to bend the rings until they disconnect from the enclosure.



WEB VERSION

3. Remove Wiring Barrier


NOTE: Pull wires through the knockouts before installing the tunnel.



4. Install Overhead Tunnel

NOTE: Pull wires through the knockouts before installing the tunnel.

NOTE: Reuse the screw removed in step 3.



Patents covering this product, if any, can be found on Leviton.com/patents.

TRADEMARK DISCLAIMER: Use herein of third party trademarks, service marks, trade names, brand names and/or product names are for informational purposes only, are/may be the trademarks of their respective owners; such use is not meant to imply affiliation, sponsorship, or endorsement.

FOR CANADA ONLY

For warranty information and/or product returns, residents of Canada should contact Leviton in writing at **Leviton Manufacturing of Canada ULC to the attention of the Quality Assurance Department, 165 Hymus Blvd, Pointe-Claire (Quebec), Canada H9R 1E9** or by telephone at **1 800 405-5320**.

LIMITED PRODUCT WARRANTY

For Leviton's limited warranty, go to www.leviton.com. For a printed copy of the warranty you may call 1-800-323-8920 or write to Leviton Manufacturing Co., Inc., Attn: Customer Service Dept., 201 North Service Road, Melville, New York 11747.